

27 □ □ □

□ □ □ □ □ □ □ □



SPRING WASHER MACHINE

Fast speed and high stability. High carbon steel with tensile strength of 1500–1700 can be used as material of spring washer.



Coil collection



Belt wire drawing machine



Coil machine



Cutting machine

- Professional
- Good quality
- Energy conservation

20 YEARS

20 years of professional export

SPRING WASHER

Ensure the quality of products, the production of excellent quality of finished products



ACCESSORIES



PRODUCT DISPLAY



Belt Wire Drawing Machine



Die for Belt Wire Drawing



Coil machine



Coil Collection Machine




Cutting Machine




Washer Tempering Furnace

MACHINE MAINTENANCE




Coil machine daily maintenance:

- 1) Jaw chuck washes it once a month, add high temperature yellow oil (300°C) . Yellow oil see the photo
- 2) Jaw chuck need to add high temperature yellow oil (300°C) every week.
- 3) every day clean the machine.



Coil machine




Leader wire




Yellow oil

Cutting machine Maintenance:

1. slide, each support part, wheel, rod, chains, copper bush add oil two time per day (morning and noon.)
2. Each day clean the machine when off duty.



cutting machine



18-22mm Cutting Machine



3-5mm Cutting Machine




10-12mm Cutting Machine



24-30mm Cutting Machine



14-16mm Cutting Machine



Belt Wire Drawing Machine




160mm-200mm Die for Belt Wire Drawing



Belt Wire Drawing Machine



3-6mm Rolling up Machine



12-16mm-18-22mm
Rolling up Machine



37kw Washer
Tempering Furnace



3-5mm-6mm-8-10mm
Coil Collection Machine



12-16mm-18-22mm-
24-30mm Coil Collection Machine