


Product Description



SPRING WASHER MACHINE

Fast speed and high stability. High carbon steel with tensile strength of 1500–1700 can be used as material of spring washer.



Coil collection



Belt wire drawing machine



Cutting machine



Coil machine

- Professional
- Good quality
- Energy conservation

20 YEARS

20 years of professional export

SPRING WASHER

Ensure the quality of products, the production
of excellent quality of finished products



ACCESSORIES



PRODUCT DISPLAY




Belt Wire Drawing Machine




Die for Belt Wire Drawing




Coil machine



Coil Collection Machine




Cutting Machine




Washer Tempering Furnace

MACHINE MAINTENANCE




Coil machine daily maintenance:

- 1) Jaw chuck washes it once a month, add high temperature yellow oil (300°C) . Yellow oil see the photo
- 2) Jaw chuck need to add high temperature yellow oil (300°C) every week.
- 3) every day clean the machine.



Coil machine




Leader wire



Yellow oil

Cutting machine Maintenance:

1. slide, each support part, wheel, rod, chains, copper bush add oil two time per day (morning and noon.)
2. Each day clean the machine when off duty.



cutting machine