

- 3. 000000 0000 0 00000



何角/真图度/内径/外径 Chamler/Roundness/ Internal/External



表面聚纹 Surface crack



孔径 Aperture



内倒角 Inner bevel



对角/对边 Cacross Comer/Across Flat




孔径/宽度/长度 Aperture / width / length



有无文字 Head Mark



多个孔径 Multiple aperture



焊点高度 The solder joint height



高度、外径 Height, diameter



缺角 Hom




焊点面积 welding points area



倒角直径 Chamfer diameter



花瓣尺寸 Petal size



有无牙/牙距/牙数 WThrood Yos or No Pitch Diamater/Thread Number



插槽宽度 Slot width

